

| Fraction | Decimal | MM      |
|----------|---------|---------|
| 1/64     | 0.0156  | 0.3969  |
| 1/32     | 0.0313  | 0.7938  |
| 3/64     | 0.0469  | 1.1906  |
| 1/16     | 0.0625  | 1.5875  |
| 5/64     | 0.0781  | 1.9844  |
| 3/32     | 0.0938  | 2.3813  |
| 7/64     | 0.1094  | 2.7781  |
| 1/8      | 0.1250  | 3.1750  |
| 9/64     | 0.1406  | 3.5719  |
| 5/32     | 0.1563  | 3.9688  |
| 11/64    | 0.1719  | 4.3656  |
| 3/16     | 0.1875  | 4.7625  |
| 13/64    | 0.2031  | 5.1594  |
| 7/32     | 0.2188  | 5.5563  |
| 15/64    | 0.2344  | 5.9531  |
| 1/4      | 0.2500  | 6.3500  |
| 17/64    | 0.2656  | 6.7469  |
| 9/32     | 0.2813  | 7.1438  |
| 19/64    | 0.2969  | 7.5406  |
| 5/16     | 0.3125  | 7.9375  |
| 21/64    | 0.3281  | 8.3344  |
| 11/32    | 0.3438  | 8.7313  |
| 23/64    | 0.3594  | 9.1281  |
| 3/8      | 0.3750  | 9.5250  |
| 25/64    | 0.3906  | 9.9219  |
| 13/32    | 0.4063  | 10.3188 |
| 27/64    | 0.4219  | 10.7156 |
| 7/16     | 0.4375  | 11.1125 |
| 29/64    | 0.4531  | 11.5094 |
| 15/32    | 0.4688  | 11.9063 |
| 31/64    | 0.4844  | 12.3031 |
| 1/2      | 0.5000  | 12.7000 |
| 33/64    | 0.5156  | 13.0969 |
| 17/32    | 0.5313  | 13.4938 |
| 35/64    | 0.5469  | 13.8906 |
| 9/16     | 0.5625  | 14.2875 |
| 37/64    | 0.5781  | 14.6844 |
| 19/32    | 0.5938  | 15.0813 |
| 39/64    | 0.6094  | 15.4781 |
| 5/8      | 0.6250  | 15.8750 |
| 41/64    | 0.6406  | 16.2719 |
| 21/32    | 0.6563  | 16.6688 |
| 43/64    | 0.6719  | 17.0656 |
| 11/16    | 0.6875  | 17.4625 |
| 45/64    | 0.7031  | 17.8594 |
| 23/32    | 0.7188  | 18.2563 |
| 47/64    | 0.7344  | 18.6531 |
| 3/4      | 0.7500  | 19.0500 |
| 49/64    | 0.7656  | 19.4469 |
| 25/32    | 0.7813  | 19.8438 |
| 51/64    | 0.7969  | 20.2406 |
| 13/16    | 0.8125  | 20.6375 |
| 53/64    | 0.8281  | 21.0344 |
| 27/32    | 0.8438  | 21.4313 |
| 55/64    | 0.8594  | 21.8281 |
| 7/8      | 0.8750  | 22.2250 |
| 57/64    | 0.8906  | 22.6219 |
| 29/32    | 0.9063  | 23.0188 |
| 59/64    | 0.9219  | 23.4156 |
| 15/16    | 0.9375  | 23.8125 |
| 61/64    | 0.9531  | 24.2094 |
| 31/32    | 0.9688  | 24.6063 |
| 63/64    | 0.9844  | 25.0031 |
| 1        | 1.0000  | 25.4000 |

| Fraction | Decimal | MM      |
|----------|---------|---------|
| 1 1/64   | 1.0156  | 25.7969 |
| 1 1/32   | 1.0313  | 26.1938 |
| 1 3/64   | 1.0469  | 26.5906 |
| 1 1/16   | 1.0625  | 26.9875 |
| 1 5/64   | 1.0781  | 27.3844 |
| 1 3/32   | 1.0938  | 27.7813 |
| 1 7/64   | 1.1094  | 28.1781 |
| 1 1/8    | 1.1250  | 28.5750 |
| 1 9/64   | 1.1406  | 28.9719 |
| 1 5/32   | 1.1563  | 29.3688 |
| 1 11/64  | 1.1719  | 29.7656 |
| 1 3/16   | 1.1875  | 30.1625 |
| 1 13/64  | 1.2031  | 30.5594 |
| 1 7/32   | 1.2188  | 30.9563 |
| 1 15/64  | 1.2344  | 31.3531 |
| 1 1/4    | 1.2500  | 31.7500 |
| 1 17/64  | 1.2656  | 32.1469 |
| 1 9/32   | 1.2813  | 32.5438 |
| 1 19/64  | 1.2969  | 32.9406 |
| 1 5/16   | 1.3125  | 33.3375 |
| 1 21/64  | 1.3281  | 33.7344 |
| 1 11/32  | 1.3438  | 34.1313 |
| 1 23/64  | 1.3594  | 34.5281 |
| 1 3/8    | 1.3750  | 34.9250 |
| 1 25/64  | 1.3906  | 35.3219 |
| 1 13/32  | 1.4063  | 35.7188 |
| 1 27/64  | 1.4219  | 36.1156 |
| 1 7/16   | 1.4375  | 36.5125 |
| 1 29/64  | 1.4531  | 36.9094 |
| 1 15/32  | 1.4688  | 37.3063 |
| 1 31/64  | 1.4844  | 37.7031 |
| 1 1/2    | 1.5000  | 38.1000 |
| 1 33/64  | 1.5156  | 38.4969 |
| 1 17/32  | 1.5313  | 38.8938 |
| 1 35/64  | 1.5469  | 39.2906 |
| 1 9/16   | 1.5625  | 39.6875 |
| 1 37/64  | 1.5781  | 40.0844 |
| 1 19/32  | 1.5938  | 40.4813 |
| 1 39/64  | 1.6094  | 40.8781 |
| 1 5/8    | 1.6250  | 41.2750 |
| 1 41/64  | 1.6406  | 41.6719 |
| 1 21/32  | 1.6563  | 42.0688 |
| 1 43/64  | 1.6719  | 42.4656 |
| 1 11/16  | 1.6875  | 42.8625 |
| 1 45/64  | 1.7031  | 43.2594 |
| 1 23/32  | 1.7188  | 43.6563 |
| 1 47/64  | 1.7344  | 44.0531 |
| 1 3/4    | 1.7500  | 44.4500 |
| 1 49/64  | 1.7656  | 44.8469 |
| 1 25/32  | 1.7813  | 45.2438 |
| 1 51/64  | 1.7969  | 45.6406 |
| 1 13/16  | 1.8125  | 46.0375 |
| 1 53/64  | 1.8281  | 46.4344 |
| 1 27/32  | 1.8438  | 46.8313 |
| 1 55/64  | 1.8594  | 47.2281 |
| 1 7/8    | 1.8750  | 47.6250 |
| 1 57/64  | 1.8906  | 48.0219 |
| 1 29/32  | 1.9063  | 48.4188 |
| 1 59/64  | 1.9219  | 48.8156 |
| 1 15/16  | 1.9375  | 49.2125 |
| 1 61/64  | 1.9531  | 49.6094 |
| 1 31/32  | 1.9688  | 50.0063 |
| 1 63/64  | 1.9844  | 50.4031 |
| 2        | 2.0000  | 50.8000 |

| Fraction | Decimal | MM      |
|----------|---------|---------|
| 2 1/64   | 2.0156  | 51.1969 |
| 2 1/32   | 2.0313  | 51.5938 |
| 2 3/64   | 2.0469  | 51.9906 |
| 2 1/16   | 2.0625  | 52.3875 |
| 2 5/64   | 2.0781  | 52.7844 |
| 2 3/32   | 2.0938  | 53.1813 |
| 2 7/64   | 2.1094  | 53.5781 |
| 2 1/8    | 2.1250  | 53.9750 |
| 2 9/64   | 2.1406  | 54.3719 |
| 2 5/32   | 2.1563  | 54.7688 |
| 2 11/64  | 2.1719  | 55.1656 |
| 2 3/16   | 2.1875  | 55.5625 |
| 2 13/64  | 2.2031  | 55.9594 |
| 2 7/32   | 2.2188  | 56.3563 |
| 2 15/64  | 2.2344  | 56.7531 |
| 2 1/4    | 2.2500  | 57.1500 |
| 2 17/64  | 2.2656  | 57.5469 |
| 2 9/32   | 2.2813  | 57.9438 |
| 2 19/64  | 2.2969  | 58.3406 |
| 2 5/16   | 2.3125  | 58.7375 |
| 2 21/64  | 2.3281  | 59.1344 |
| 2 11/32  | 2.3438  | 59.5313 |
| 2 23/64  | 2.3594  | 59.9281 |
| 2 3/8    | 2.3750  | 60.3250 |
| 2 25/64  | 2.3906  | 60.7219 |
| 2 13/32  | 2.4063  | 61.1188 |
| 2 27/64  | 2.4219  | 61.5156 |
| 2 7/16   | 2.4375  | 61.9125 |
| 2 29/64  | 2.4531  | 62.3094 |
| 2 15/32  | 2.4688  | 62.7063 |
| 2 31/64  | 2.4844  | 63.1031 |
| 2 1/2    | 2.5000  | 63.5000 |
| 2 33/64  | 2.5156  | 63.8969 |
| 2 17/32  | 2.5313  | 64.2938 |
| 2 35/64  | 2.5469  | 64.6906 |
| 2 9/16   | 2.5625  | 65.0875 |
| 2 37/64  | 2.5781  | 65.4844 |
| 2 19/32  | 2.5938  | 65.8813 |
| 2 39/64  | 2.6094  | 66.2781 |
| 2 5/8    | 2.6250  | 66.6750 |
| 2 41/64  | 2.6406  | 67.0719 |
| 2 21/32  | 2.6563  | 67.4688 |
| 2 43/64  | 2.6719  | 67.8656 |
| 2 11/16  | 2.6875  | 68.2625 |
| 2 45/64  | 2.7031  | 68.6594 |
| 2 23/32  | 2.7188  | 69.0563 |
| 2 47/64  | 2.7344  | 69.4531 |
| 2 3/4    | 2.7500  | 69.8500 |
| 2 49/64  | 2.7656  | 70.2469 |
| 2 25/32  | 2.7813  | 70.6438 |
| 2 51/64  | 2.7969  | 71.0406 |
| 2 13/16  | 2.8125  | 71.4375 |
| 2 53/64  | 2.8281  | 71.8344 |
| 2 27/32  | 2.8438  | 72.2313 |
| 2 55/64  | 2.8594  | 72.6281 |
| 2 7/8    | 2.8750  | 73.0250 |
| 2 57/64  | 2.8906  | 73.4219 |
| 2 29/32  | 2.9063  | 73.8188 |
| 2 59/64  | 2.9219  | 74.2156 |
| 2 15/16  | 2.9375  | 74.6125 |
| 2 61/64  | 2.9531  | 75.0094 |
| 2 31/32  | 2.9688  | 75.4063 |
| 2 63/64  | 2.9844  | 75.8031 |
| 3        | 3.0000  | 76.2000 |